



Project Number LWYL 1498

Project Inspection Sheet

Address: 1768 FIRESIDE DR.	
Property Elements	Comments
Exterior Walls/ Paint/ Siding	
Roof/ Gutter/ Downspout/ Chimney	
Windows/Doors	
Facia/Soffit	
Yard	
Trees/Shrubs	Front Trees Need Minor Trimming Back Tree Needs Trimming @ Roof Line Clean out Flowerbeds of Overgrowth, Trim Shrubs
Trash/Clutter/Debris	Remove Pile of Old Wood in Backyard – Some of the wood is still good but the homeowner does not want or need it – City of Plano large trash department told her the wood was too long for them to help haul it off
Accessory Building/ Fence	Several Loose Pickets on Fence Gate Hardware is not locking – need adjusted Need 1 new post @ lean – maybe a 2x4 rai
Other noticeable concerns (foundation, overall yard condition)	



